



In re Patent of:)	
ICHIRO NOMURA ET AL.		:	Examiner: D. Dong
)	C A I I 2070
Appln. No.: 09/809,055		;	Group Art Unit: 2879
F F		:	
Filed: March 16, 2001)	
For:	METHOD AND APPARATUS FOR	:	Certificate
roi.)	
	MANUFACTURING IMAGE	:	JUL 2 2 2005
	DISPLAYING APPARATUS)	
		:	of Correction
U.S. Patent No.: 6,848,961 B2)	
		:	
Issued:	February 1, 2005)	July 18, 2005

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION <u>UNDER RULES 322 AND 323</u>

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

07/20/2005 SSITHIB1 00000061 6848961 01 FC:1811 100.00 OP

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Attorney for Patentees Registration No. 29,296

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 Facsimile: (212) 218-2200

NY_Main 511236v1

CERTIFICATE OF CORRECTION

PATENT NO.

US 6.848,961 B2

DATED

February 1, 2005

INVENTOR(S) :

ICHIRO NOMURA ET AL.

Page 1 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE TITLE PAGE [57] ABSTRACT:

Line 6, "substrate. While," should read --substrate, while--.

COLUMN 2:

Line 22, ""FP")" should read --as "FP")--;

Line 28, "requires" should read --requires a--;

Line 30, "inside" should read -- the inside--;

Line 31, "10-6 Pa" should read 10-6 Pa; and

Line 40, "are" should be deleted.

COLUMN 3:

Line 3, "a manufacturing" should read --manufacturing--;

Line 12, "connected" should read -- are connected--;

Line 16, "whereby" should read --thereby--:

Line 27, "a gettering" should read --performing a gettering-- and

"is performed" should be deleted; and

Line 45, "whereby" should read --thereby--.

COLUMN 4:

Line 61, "a of" should read -- another mode of--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

PATENT NO. <u>US 6,848,961 B2</u>

No. of add'l. copies @ 30¢ per page

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,848,961 B2

DATED

February 1, 2005

INVENTOR(S) :

ICHIRO NOMURA ET AL.

Page 2 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 5:

Line 36, "connected" should read -- are connected--;

Line 41, "whereby" should read --thereby--;

Line 47, "are disposed" should be deleted;

Line 52, "a gettering" should read --performing a gettering-- and

"is performed" should be deleted; and

Line 58, "Secondary," should read -- Secondarily, --.

COLUMN 6:

Line 5, "whereby" should read --thereby--.

COLUMN 8:

Line 34, "arrange" should read --arranged--;

Line 44, "region" should read -- the region--;

Line 45, "air-tight" should read --airtight--; and

Line 46, "wiring" should read -- the wiring--.

COLUMN 9:

Line 29, "under setting" should read --where--;

Line 30, "into" should read --is under--;

Line 31, "under setting" should read --where--;

Line 32, "into" should read --is under--; and

Line 52, "means" should read --is defined as--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) NY_Main 511236v1

PATENT NO. US 6,848,961 B2

No. of add'l. copies @ 30¢ per page



CERTIFICATE OF CORRECTION

PATENT NO.

US 6,848,961 B2

DATED

February 1, 2005

INVENTOR(S) :

ICHIRO NOMURA ET AL.

Page 3 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 10:

Line 5, "gage;" should read --gauge;-- and "an drawing" should read --a drawing--;

Line 48, "that" should read --in which--; and

Line 60, "that" should read --in which--.

COLUMN 11:

Line 27, "(en" should read --(an--;

Line 31, "case" should read --case in which--;

Line 32, "member" should read --members--;

Line 39, "hardly deform" should read --more difficult to deform--; and

Line 44, "case" should read --case in which--.

COLUMN 12:

Line 19, "with" (second occurrence) should read --with substances--;

Line 21, "apply" should read --application--;

Line 35, "CnH₂n⁺² of" should read --CnH₂n⁺²,--;

Line 37, "CnH₂n etc." should read --CnH₂n,--; and

Line 54, "by such as" should read --of--.

COLUMN 13:

Line 1, "gases" should read --gas--; and Line 27, "is used." should read --are used.--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) NY_Main 511236v1 PATENT NO. US 6,848,961 B2

No. of add'l. copies @ 30¢ per page



CERTIFICATE OF CORRECTION

PATENT NO.

US 6,848,961 B2

DATED

February 1, 2005

INVENTOR(S) :

ICHIRO NOMURA ET AL.

Page 4 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 14:

Line 65, "replace" should read --replacement--.

COLUMN 15:

Line 43, "used, however," should read --used. However,--.

COLUMN 17:

Line 50, "moves" should read --move--; and Lines 64-65, "thereby vacuum exhausing" should read --thereby creating vacuum--.

COLUMN 18:

Line 11, "carried in" should read --carried into--;

Line 16, "subject to" should read --subjected to--; and

Line 52, "range of" should read --range where it is--.

COLUMN 19:

Line 12, "a evaporable" should read -- an evaporable--;

Line 26, "a electrostatic" should read -- an electrostatic--; and

Line 37, "fist" should read --first--.

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,848,961 B2</u>

No. of add'l. copies @ 30¢ per page

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,848,961 B2

DATED

February 1, 2005

INVENTOR(S) :

ICHIRO NOMURA ET AL.

Page 5 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 20:

Line 24, "in" should read --into--;

Line 27, "is arranged" should read -- are arranged--;

Line 29, "contacts" should read --contact--;

Line 32, "toward inside" should read --toward the inside--; and

Line 58, "withing" should read --within--.

COLUMN 21:

Line 1, "carried in" should read --being carried into--;

Line 5, "inside" should read -- the inside--;

Line 14, "proceed" should read --proceed with--;

Line 27, "AS" should read -- As--;

Line 28, "proceed" should read --proceed with--; and

Line 51, "207" should read --2207--.

COLUMN 22:

Line 5, "one of substrates on both substrates" should read -- one of the substrates--;

Line 42, "the devices" should read --devices--;

Line 47, "existing" should read --causing--;

Line 48, "technique" should read --steps--;

Line 50, "sides. Embodiments" should read --sides. ¶(no indent)

EMBODIMENTS-- and "The" should read -- The--.

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,848,961 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

NY_Main 511236v1

No. of add'i. copies @ 30¢ per page



CERTIFICATE OF CORRECTION

PATENT NO.

US 6,848,961 B2

DATED

February 1, 2005

INVENTOR(S) :

ICHIRO NOMURA ET AL.

Page 6 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 23:

Line 27, "caused" should read --be caused--; and Line 55, "to" should be deleted.

COLUMN 24:

Line 9, "to" should be deleted.

COLUMN 25:

Line 32, "the activation" should read -- an activation--.

COLUMN 26:

Line 44, "that" should read --wherein--.

COLUMN 27:

Line 30, "IF" should read --If--.

COLUMN 28:

Line 12, "The" should read -- An--; and

Line 29, "as in the same manner in" should read --in the same manner as in--.

COLUMN 29:

Line 31, "on" should be deleted.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies

PATENT NO. <u>US 6,848,961 B2</u>

@ 30¢ per page



CERTIFICATE OF CORRECTION

PATENT NO.

US 6,848,961 B2

DATED

February 1, 2005

INVENTOR(S) :

ICHIRO NOMURA ET AL.

Page 7 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 30:

Line 11, " $Sd = SO \times [1 + (d/L)]\frac{1}{2}$ " should read -- $Sd = SO \times [1 + (d/L)2]\frac{1}{2}$ --.

COLUMN 36:

Line 33, "an" should read --a--.

COLUMN 37:

Line 62, "manufacture." should read --manufactured.--.

COLUMN 38:

Line 3, "manufacture" should read --manufacturing--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) NY Main 511236v1 PATENT NO. <u>US 6,848,961 B2</u>

No. of add'l. copies @ 30¢ per page



CERTIFICATE OF CORRECTION

PATENT NO.

US 6,848,961 B2

DATED

February 1, 2005

INVENTOR(S) :

ICHIRO NOMURA ET AL.

Page 1 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE TITLE PAGE [57] ABSTRACT:

Line 6, "substrate. While," should read --substrate, while--.

COLUMN 2:

Line 22, ""FP")" should read --as "FP")--;

Line 28, "requires" should read --requires a--;

Line 30, "inside" should read -- the inside--:

Line 31, "10-6 Pa" should read 10-6 Pa; and

Line 40, "are" should be deleted.

COLUMN 3:

Line 3, "a manufacturing" should read --manufacturing--;

Line 12, "connected" should read -- are connected--;

Line 16, "whereby" should read --thereby--;

Line 27, "a gettering" should read --performing a gettering-- and

"is performed" should be deleted; and

Line 45, "whereby" should read --thereby--.

COLUMN 4:

Line 61, "a of" should read -- another mode of--.

MAILING ADDRESS OF SENDER:


FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

PATENT NO. <u>US 6,848,961 B2</u>

No. of add'l. copies @ 30¢ per page





CERTIFICATE OF CORRECTION

PATENT NO.

US 6,848,961 B2

DATED

February 1, 2005

INVENTOR(S) :

ICHIRO NOMURA ET AL.

Page 2 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 5:

Line 36, "connected" should read -- are connected--;

Line 41, "whereby" should read --thereby--;

Line 47, "are disposed" should be deleted;

Line 52, "a gettering" should read --performing a gettering-- and "is performed" should be deleted; and

Line 58, "Secondary," should read -- Secondarily, --.

COLUMN 6:

Line 5, "whereby" should read --thereby--.

COLUMN 8:

Line 34, "arrange" should read --arranged--;

Line 44, "region" should read -- the region--;

Line 45, "air-tight" should read --airtight--; and

Line 46, "wiring" should read -- the wiring--.

COLUMN 9:

Line 29, "under setting" should read --where--;

Line 30, "into" should read --is under--;

Line 31, "under setting" should read --where--;

Line 32, "into" should read -- is under--; and

Line 52, "means" should read -- is defined as--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) NY_Main 511236v1 PATENT NO. _US 6,848,961 B2

No. of add'l. copies @ 30¢ per page

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,848,961 B2

DATED

February 1, 2005

INVENTOR(S) :

ICHIRO NOMURA ET AL.

Page 3 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 10:

Line 5, "gage;" should read --gauge;-- and "an drawing" should read --a drawing--;

Line 48, "that" should read --in which--; and

Line 60, "that" should read --in which--.

COLUMN 11:

Line 27, "(en" should read --(an--;

Line 31, "case" should read --case in which--;

Line 32, "member" should read --members--;

Line 39, "hardly deform" should read --more difficult to deform--; and

Line 44, "case" should read --case in which--.

COLUMN 12:

Line 19, "with" (second occurrence) should read --with substances--;

Line 21, "apply" should read --application--;

Line 35, " CnH_2n^{+2} of" should read -- CnH_2n^{+2} ,--;

Line 37, "CnH₂n etc." should read --CnH₂n,--; and

Line 54, "by such as" should read -- of--.

COLUMN 13:

Line 1, "gases" should read --gas--; and Line 27, "is used." should read --are used.--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) NY_Main 511236v1 PATENT NO. _US 6,848,961 B2

No. of add'l. copies @ 30¢ per page

Staple Here Only! WINTER'S TRIM HER'S TRIM H

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

US 6,848,961 B2

DATED

February 1, 2005

INVENTOR(S) :

ICHIRO NOMURA ET AL.

Page 4 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 14:

Line 65, "replace" should read --replacement--.

COLUMN 15:

Line 43, "used, however," should read --used. However,--.

COLUMN 17:

Line 50, "moves" should read --move--; and Lines 64-65, "thereby vacuum exhausing" should read --thereby creating vacuum--.

COLUMN 18:

Line 11, "carried in" should read --carried into--;

Line 16, "subject to" should read -- subjected to--; and

Line 52, "range of" should read --range where it is--.

COLUMN 19:

Line 12, "a evaporable" should read -- an evaporable--;

Line 26, "a electrostatic" should read -- an electrostatic--; and

Line 37, "fist" should read --first--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. <u>US 6,848,961 B2</u>

No. of add'l. copies @ 30¢ per page

300

JUL 2 5 2005

Form PTO 1050 (Rev. 3-82) NY Main 511236v1

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,848,961 B2

DATED

February 1, 2005

INVENTOR(S) :

ICHIRO NOMURA ET AL.

Page 5 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 20:

Line 24, "in" should read --into--;

Line 27, "is arranged" should read -- are arranged--;

Line 29, "contacts" should read --contact--;

Line 32, "toward inside" should read --toward the inside--; and

Line 58, "withing" should read --within--.

COLUMN 21:

Line 1, "carried in" should read --being carried into--;

Line 5, "inside" should read -- the inside--;

Line 14, "proceed" should read --proceed with--;

Line 27, "AS" should read -- As--;

Line 28, "proceed" should read --proceed with--; and

Line 51, "207" should read --2207--.

COLUMN 22:

Line 5, "one of substrates on both substrates" should read -- one of the substrates--;

Line 42, "the devices" should read --devices--;

Line 47, "existing" should read --causing--;

Line 48, "technique" should read --steps--;

Line 50, "sides. Embodiments" should read --sides. ¶(no indent) EMBODIMENTS-- and "The" should read --¶ The--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. <u>US 6,848,961 B2</u>

No. of add'l. copies @ 30¢ per page

138138**3**

Form PTO 1050 (Rev. 3-82)

NY_Main 511236v1

Staple Here Only! NIZE S. WELL S. WELL

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 6,848,961 B2

DATED

February 1, 2005

INVENTOR(S) :

ICHIRO NOMURA ET AL.

Page 6 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 23:

Line 27, "caused" should read --be caused--; and Line 55, "to" should be deleted.

COLUMN 24:

Line 9, "to" should be deleted.

COLUMN 25:

Line 32, "the activation" should read -- an activation--.

COLUMN 26:

Line 44, "that" should read --wherein--.

COLUMN 27:

Line 30, "IF" should read --If--.

COLUMN 28:

Line 12, "The" should read -- An--; and

Line 29, "as in the same manner in" should read --in the same manner as in--.

COLUMN 29:

Line 31, "on" should be deleted.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

PATENT NO. US 6,848,961 B2

No. of add'l. copies @ 30¢ per page



CERTIFICATE OF CORRECTION

PATENT NO.

US 6,848,961 B2

DATED

February 1, 2005

INVENTOR(S) :

ICHIRO NOMURA ET AL.

Page 7 of 7

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 30:

Line 11, " $Sd = SO \times [1 + (d/L)]\frac{1}{2}$ " should read -- $Sd = SO \times [1 + (d/L)2]\frac{1}{2}$ --.

COLUMN 36:

Line 33, "an" should read --a--.

COLUMN 37:

Line 62, "manufacture." should read --manufactured.--.

COLUMN 38:

Line 3, "manufacture" should read --manufacturing--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. <u>US 6,848,961 B2</u>

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82) NY_Main 511236v1